

# FLEET LOGISTICS SUPPORT IMPROVEMENT CONFERENCE (FLSIC) NSA ILS IPT BRIEF

Rosemary Travis
14 March 2001

## **TOPICS**

Background

Approach

Results

Summary

#### BACKGROUND

#### COMNAVSURFPAC MSG DTG 082034Z OCT 99

 Lack of support for A/C Plant installations on five LPD-4 Class ships

#### COMNAVSURFPAC MSG DTG 010057Z NOV 99

- Incomplete configuration change reporting for West Coast AOE Class ships. Configuration reporting not occurring within 30 day timeframe after EOA

#### COMNAVSURFLANT MSG DTG 172130Z DEC 99

 Incomplete NSA Configuration Reporting for MCM and MHC Class ships





#### **APPROACH**

 Logistics Review Team (LRT) appointed by NAVSEA 04L5 to conduct on-site NSA ILS assessments (MSG DTG 080428Z FEB 00); investigate/resolve deficiencies sited in Fleet messages

#### • LRT:

- NAVSEA 04L4/L5 representatives
- NSLC FSO JAX
- Puget Sound Naval Shipyard (PSNSY)
- SURFLANT representative

# PHASE I

• LRT TO SUPSHIP SAN DIEGO AND SUPSHIP JACKSONVILLE DET INGLESIDE

• REVIEW OVERALL ILS OPERATIONS, PROCESSES AND PROCEDURES

• IDENTIFY /RESOLVE REPORTED DEFICIENCIES - COMPLETE!

# PHASE II

- EXAMINE FMP NSA ILS SUPPORT OPERATIONS, PROCESSES AND PROCEDURES
- IDENTIFY SYSTEMIC ISSUES AND VIABLE ALTERNATIVES
- IMPLEMENT AFFORDABLE SOLUTIONS

### LRT SITE VISITS





#### RESULTS

- •Total Findings: 28 Recommendations: 40
- Categories
  - -Manning/Organization
  - -Policy
  - -AIS
  - -Metrics
  - -Process

# MANNING/ORGANIZATI

#### Major Findings:

- -Inadequate staffing at NSAs
- -Realignment of functions, PEO/contractor resource augmentation
- -Variation in functional knowledge and use of standard tools
- -Lack of training
- No standard procedure/organization responsibility for enforcement of AIT logistics product delivery inside/outside availabilities

# PORT LOADING &LOGISTICS MANNING

PORT	NUMBER OF SHIPS	TOTAL LOGISTICS PERSONNEL (NSA)
SAN DIEGO	58	47 (9)
NORFOLK /LITTLE CREEK	87	44 (4)
NEWPORT NEWS	1	20 (20)
EARLE	4	0
BREMERTON AREA	14	20 (8)
MAYPORT	19	14 (1)
PASCAGOULA	6	8 (5)
INGLESIDE	21	9 (4)
PEARL HARBOR	31	28 (4)
GROTON	15	20 (16)

# MANNING/ORGANIZATI

- •Recommendations
  - -Revise policy documents to realign functions/responsibilities (FMP Manual in-progress, others pending ECD 6/1)
  - -Resolve East/West Coast differences for AITs and standardize SUPSHIP responsibilities (RMMCO agreements pending, ECD 6/1)
  - -Develop a "regional" logistics/Port Logistician solution vice ship class/PEO specific (Pilots in JAX, Ingleside, San Diego ECD 12/31)

# MANNING/ORGANIZATI

- Recommendations/Status:
  - -Establish procedures to review, assess, and certify performance of ILS logistics/configuration management responsibilities (NAVSEA 04L, ECD -6/30)
  - -Ensure adequate logistics coverage for AIT installations (Included in Port Logistician solution and RMMCO standard procedures, ECD-12/31)
  - -Require use of standard tools and development of functional knowledge (FMP policy revision, regional logistics solution, ECD- 12/31)

#### Major Findings:

- -Lack of CNO waivers and standard procedures for tracking/resolving ILS deficiencies
- -ILS certifications not provided to waterfront
- -Conflicting policy guidance &COTS policy not adequately promulgated
- -NAVSEA Standard Items require revision
- -Lack of configuration change reporting and ILS for IMA/FMA installations
- No contractor incentive for procurement of standard Navy equipment
- -Submarines exempt from NAVSEA Standard Items and policy documents

- Recommendations/Status:
  - -Revise FMP policy to address "conditional" approval by SPMs vice "ILS waiver" and tracking/resolution of ILS deficiencies (FMP revision in progress, ECD- 6/30)
  - -Revise policy to require ILS certification for all alterations (FMP revision in progress, ECD- 6/30)
  - -Ensure inclusion of ILS certification information and tracking capability in NDE (Partial inclusion in the NDE AMP module with planned completion in the NDE ILS module, ECD - 6/30)

#### •Recommendations/Status:

- -Revise/align all policy documents (NAVSEA 04L5 coordinate, ECD -9/30)
- -Include/reference in other policy documents the NAVSEA COTS policy (FMP revision in progress, NAVSEA 04L5 lead, ECD 9/30
- -Update NAVSEA Standard Items to clearly define and ensure delivery of required configuration and logistics products (Completed, 11/00)
- -Clarify/invoke standard configuration change reporting and ILS delivery requirements for IMA/FMA installations (FMP in progress, Tech Spec 9090-310C required, ECD-6/30

- Recommendations/Status:
  - -Develop contractual language to encourage procurement of Navy standard equipment (NAVSEA 04L5, ECD - 6/30)
  - -Investigate how ILS requirements are invoked for submarine availabilities (NAVSEA 04L5, ECD 6/30)

#### **AIS**

# • Major Findings:

- -TDMIS not consistently being updated by ISEAs
- -Multiple databases used for tracking of ILS requirements and deliverables
- -Standard AIS tools not fully utilized at all sites (i.e.CDMD-OA, ICAPS)

#### **AIS**

# •Recommendations/Status.

- -Ensure timely update of TDMIS and inclusion in ISEA logistics assessment process currently being developed (NAVSEA 04L1/04L5, ECD 6/30)
- -Include ILS tracking in functional requirements for NDE ILS module (NAVSEA 04L5/04M3, ECD 6/30)
- -Revise policy documents to require use of standard logistics/configuration AIS tools (FMP/SCLSIS Tech Spec revisions in progress, ECD 6/30

#### **METRICS**

#### Major Findings:

 No collection of ILS metrics on the waterfront to assess impact of unsupported alterations on Fleet readiness

#### Recommendations/Status:

-Establish standard role-based metrics to support trend analysis and process improvement(NAVSEA 04M3 functional requirement for NDE AMP module, NAVSEA 04L1/04L5 coordinating with Fleet Metrics groups, ECD - 9/30)

- Major Findings:
  - -Multiple ship in-briefs
  - -Lack of standard SPM ILS procedures across ship platforms (i.e. ILSMTs, ILO/ILR process)
  - -Redundancy in validation efforts
  - -Inconsistency in COP development
  - -Post Availability Logistics Support (PALS) effort limited scope
  - -AIT violation of established procedures
  - -Inability to accurately assess configuration accuracy and attainment of established goals

- Recommendations/Status:
  - -Provide one comprehensive logistics in-brief to ship at SOA (included in Regional/Port Logistician solution currently being developed, ECD - 6/30)
  - -Encourage use of ILSMTs by all SPMS and standard ILO/ILR process for all ship platforms(NAVSEA 04L5 coordinate with SPMs, ECD 9/30)
  - -Eliminate validation redundancies and maximize effective utilization of available resources (NAVSEA 04L5 sponsored Validation Working Group, ECD 6/30)

- Recommendations/Status:
  - -Develop/promulgate standard COP policy/procedures (NAVSEA 04L5 sponsored CDM/ISEA Working Group, FMP revision, ECD 6/30)
  - -Expand PALS scope beyond Planned Adds to include emergent and AIT work (NAVSEA 04L4/04L5, ECD -9/30)

- Recommendations/Status:
  - -Investigate use of Smart Card technology to control ship access by AITs (NAVSEA 04L5, ECD - 9/30)
  - -Investigate use of RFID technology to enhance configuration control and accuracy
  - -(NAVSEA 04L5 coordinate with NAVAIR/NAVSUP, ECD 9/30

#### **SUMMARY**

- •Initial regional ILS assessment conducted
- •Establish metrics and Measures of Effectiveness
- Baseline current status
- •Complete required process reengineering
- Follow-up assessment

#### Assessment and Metrics